










175/177/179 True-rms Multimeter

  www.fluke.com








(179)




→ OK



→ OK



→ OK



→ OK

